

## Under Review Notification

**Raised By:** VANESSA MOREL

**Product #:** DART TOOLING EUROCOPTER

**Date:** 17.12.14

**Product Name:** SEAL EXTRACTOR

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
RBEM632V3009126	RBEM632V3009126 REV 1	Y	Y	N	N	Y	Y	Y	17-742	see engineering for WO currently in progress

**Description of Issue:** PART MISSING

RBEM632V3009126: RBEM632V3009126-1 & -3 ADDED

RBEM632V3009126-3: DEVIATION SIGN AND PRODUCTION START MACHINING.

**Distribution:**

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------